



June 19<sup>th</sup>, 2012

Bob Bliss  
GSA  
400 15<sup>th</sup> St SW  
Auburn, WA, 98001

RE: Analytical Results for Total Lead  
RGA Batch # 12-1544  
Matrix – Dust Wipe


Dear Bob,

Enclosed are the results of the samples recently submitted to our laboratory for analysis. These samples were analyzed for the metals listed on the enclosed report following the specified EPA or NIOSH Method listed.

This report relates only to the items tested. If RGA Environmental personnel do not collect the samples, the accuracy of the results is limited by the methodology and the expertise of the sample collector. Quality assurance and quality control procedures for this analysis are followed in accordance with the AIHA ELLAP guidelines for lead analysis.

RGA appreciates the opportunity to be of service to you on this project, and hopes that you will consider working with our company again in the future. Please feel free to contact me if I may be of additional assistance.

Sincerely,

  
Dr. Aruna Turaga  
Laboratory Director

*enclosure: Lab Results*



June 19, 2012

## RGA Batch # 12-1544

Client: Bob Bliss  
Company: GSA  
400 15th St SW  
Auburn, WA, 98001

Project: Federal Reserve Bank, Seattle  
Matrix: Dust Wipe - Pb  
Date Sampled: 6/5/2012  
Date Received: 6/12/2012  
Date Analyzed: 6/18/2012

Project #: N/A  
P.O. #: N/A  
Sampled By: Client  
Method: NIOSH Method 7082  
Analyst: Aruna Turaga

## LEAD DUST WIPE RESULTS


RGA Lab ID	Client ID	Sample Area (sq. ft.)	RL (ug/sq.ft.)	Sample Conc. (ug/wipe.)	Sample Conc. (ug/sq.ft.)
12014716	FR-01	0.61	20	77,000	130,000
12014717	FR-02	0.50	25	180,000	360,000
12014718	FR-03	0.76	16	16,000	21,000
12014719	FR-04	0.38	33	96	250
12014720	FR-05	0.19	66	< 13	< 66

QA/QC Results  
Batch QC LCS  
Method Blank

105% Recovery  
3 ug/mL

RL - reporting limit  
ug - micrograms  
m3 - cubic meter  
< - less than

Reviewed by:

  
Dr. Aruna Turaga, Laboratory Director

RGA Environmental, Inc.  
1730 Minor Avenue, Suite 900  
Seattle, WA 98101  
www.rgaenv.com  
Ph: (206) 281-8858 Fax: (206) 281-8922

## Sample Log Chain of Custody

Client Company: GSA  
Client Address: 400 15th St SW  
Auburn WA 98001  
City State Zip

Phone #: 253-397-6862  
2nd or Cell #:  
Fax #:  
e-mail Address: robert.bliss@gsa.gov

Attention to: Bob Bliss

Project Location: Federal Reserve Bank  
Seattle

Condition: ☒ Good ☐ Damaged ☐ Severe Damage

RGA Batch #: 12-1544  
Client Job #:  
Client P.O. #:  
Number of Samples: 5

### TYPE OF ANALYSIS

ASBESTOS:	METALS: <u>lead</u>	
<input type="checkbox"/> PCM (air)	<input type="checkbox"/> Paint	<input type="checkbox"/> Soil
<input type="checkbox"/> PLM (bulk)	<input checked="" type="checkbox"/> Wipe	<input type="checkbox"/> Air
<input type="checkbox"/> Pt. Count (bulk)	<input type="checkbox"/> TCLP	<input type="checkbox"/> Water

Other (Specify Method):

Turn Around Time (other):

2 hour / 4 hour	Same Day	One Day
Two Day	3-5 days	<u>10 days</u>

Price per Sample: \$ 20.00

#	Client Sample ID	RGA Laboratory ID	Comments	#	Client Sample ID	RGA Laboratory ID	Comments
1	FR-01	12014716	0.61 ft <sup>2</sup>	11			
2	FR-02	17	0.5 ft <sup>2</sup>	12			
3	FR-03	18	0.76 ft <sup>2</sup>	13			
4	FR-04	19	0.38 ft <sup>2</sup>	14			
5	FR-05	20	0.19 ft <sup>2</sup>	15			
6				16			
7				17			
8				18			
9				19			
10				20			

	Signature	Date	Time
Sampled by:	<u>[Signature]</u>	<u>6-5-12</u>	<u>1000</u>
Relinquished by:	<u>[Signature]</u>	<u>6-12-12</u>	<u>0900</u>
Received by:			
Relinquished by:			
Received for Laboratory by:	<u>[Signature]</u>	<u>6/12/12</u>	<u>1045</u>
Analyzed by:	<u>[Signature]</u>	<u>6/12/12</u>	
Preliminary Results Reported to Client by:	<u>[Signature]</u>	<u>6/19/12</u>	
Final Report to Client by:			

Special Instructions:





**INVOICE # 12-1544**

June 19, 2012

Client: Bob Bliss  
Company: GSA  
400 15th St SW  
Auburn, WA, 98001

Attention: Accounts Payable  
Project: Federal Reserve Bank, Seattle  
Project #: N/A  
P.O. #: N/A

**LABORATORY ANALYSIS SERVICES**

Service	Date	Rate	# of Samples	Extended Price
Dust Wipe - Pb	June 19, 2012	\$20.00	5	\$100.00

**Please Pay This Amount:**

**\$100.00**


**Please Remit to:**

Department 62  
RGA Environmental, Inc.  
1466 66th Street  
Emeryville, CA 94608  
(510) 547-7771 or (800) 776-5696  
Federal Tax ID # 94-3051012

**Terms are Net upon Invoicing**



Preventive Dust work




- SERV-FLOOR COMMON.
- SERV-BUILDING COMMON.
- VERT- NON-RENT

# SEATTLE BRANCH - BASEMENT 2

Updated: 09/04/2007  
Q4/ 2007





# SEATTLE BRANCH - GROUND FLOOR

Updated: 09/04/2007

Q4/ 2007

-  SERV-FLOOR COMMON.
-  SERV-BUILDING COMMON.
-  VERT- NON-RENT

FR 01 - Floor 11x8  
 02 - Floor 6x12 interior  
 03 - w/d 11x10 - hwy file

